

Airworthiness Directive

▶ Federal Register Information

▼ Header Information

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

Amendment 39-3474; AD **79-10-16**

BOEING Model 707-300/-400/-300B/-300C Airplanes

PDF Copy (If Available):

▼ Preamble Information

AGENCY: Federal Aviation Administration, DOT

DATES: Effective June 25, 1979.

▼ Regulatory Information

79-10-16 BOEING: Amendment 39-3474. Applies to all Boeing 707-300/-400/-300B/-300C airplanes noted in Boeing Service Bulletin 3356:

No later than December 31, 1980, modify the horizontal stabilizer in accordance with the terminating action specified in Boeing Service Bulletin 3356, or in a manner approved by the Chief, Engineering and Manufacturing Branch, FAA Northwest Region.

The manufacturer's specifications and procedures identified and described in this directive are incorporated herein and made a part hereof pursuant to 5 U.S.C. 552(a)(1).

All persons affected by this directive who have not already received these documents from the manufacturer, may obtain copies upon request to the Boeing Commercial Airplane Company, P.O. Box 3707, Seattle, Washington 98124. These documents may also be examined at FAA, Northwest Region, 9010 East Marginal Way South, Seattle, Washington 98108.

This amendment becomes effective June 25, 1979.