

**Luxembourg Investigation Commission**  
**Supplemental Recommendation within Revised Accident Report**

Since a radar display is available for information only in the control tower and no procedures exist in the current department documentation to eventually take maximum advantage of such equipment, it is recommended that the authority identify if the actual set-up of the equipment could be used for surveillance and radar assistance through appropriate procedures paired with methods of utilization and training.